

FIG. 1A




FIG. 1B





FIG. 1C






FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




Fig. 9.




FIG.10




FIG. 11




Fig. 1 is a schematic diagram of a mechanical assembly. The assembly includes a base 70 with a vertical shaft 71 and a horizontal shaft 72. A motor 73 is connected to the horizontal shaft. A series of gears and shafts are shown, including components 20, 30, 40, 50, 10A, 10B, 12a, 12b, K3, K4, and Db. Arrows indicate the direction of rotation and movement.

[illegible]